

300-180^{Q&As}

Troubleshooting Cisco Data Center Infrastructure

Pass Cisco 300-180 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/300-180.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.pass4itsure.com/300-180.html

QUESTION 1

Which two options are causes for failure of a Cisco C-Series server that is configured to boot from SAN? (Choose two.)

- A. The boot LUN ID is not 0.
- B. The ISCSI target is only available via one via one path through the network.
- C. C-Series does not support boot from SAN.
- D. The KVM dongle is attached to the front of the server with a USB stick installed.
- E. Under the FCoE properties on the vNIC adapter, the FCoE VLAN ID is set to 10.
- F. The boot table for fc0 has not been configured.

Correct Answer: DF

QUESTION 2

Refer to the exhibit.

You have a server that fails to boot *which option is a possible cause of the issue?

- A. an incorrect boot policy
- B. incorrect zoning
- C. an incorrect FC/FCoE target port in the SAN
- D. incorrect LUN masking on the Storage array

Correct Answer: D

What is the default MTU size of a VMware host?

https://www.pass4itsure.com/300-180.html

2022 Latest pass4itsure 300-180 PDF and VCE dumps Download

QUESTION 3

A. 1000
B. 1500
C. 1550
D. 9000
Correct Answer: B
QUESTION 4
A customer is trying to boot an operating system that is installed on the eUSB on a Cisco UCS B-Series blade server; however, the boot fails. What is the cause of this failure?
A. The local disk must be the first device in the boot order.
B. eUSB is not a supported boot device.
C. eUSB support is available only on the Cisco UCS C-Series rack server.
D. eLISB is not the first device in the hoot order for the server

QUESTION 5

Correct Answer: D

Which statement about port channels is true?

- A. All member ports should be in up state for the port channel to be up
- B. All member ports in a port channel need not use the same speed and duplex
- C. It is recommended to make changes in the individual member ports that are part of the port channel
- D. Each port can be in only one port channel

Correct Answer: D

300-180 PDF Dumps 300-180 Study Guide 300-180 Exam Questions



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.pass4itsure.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4itsure, All Rights Reserved.