



# DES-4421<sup>Q&As</sup>

Specialist - Implementation Engineer, PowerEdge MX Modular Exam

**Pass EMC DES-4421 Exam with 100% Guarantee**

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/des-4421.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by EMC  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





### QUESTION 1

After installing a supported OS from a bootable ISO on an MX740c sled, an administrator discovers that not all the hardware is properly detected by the OS. They plan to reinstall the OS. What should the administrator do to resolve this issue through OS installation?

- A. Update the Dell OS Driver Pack and use the OS Deployment feature
- B. Modify the bootable ISO to remove faulty drivers and boot directly from the bootable ISO
- C. Modify the bootable ISO to remove faulty drivers and use the OS deployment feature
- D. Update the Dell OS Driver Pack and boot directly from the bootable ISO

Correct Answer: D

---

### QUESTION 2

What is the benefit of C22 power inlet connectors on the MX7000 chassis?

- A. Meet higher power requirements
- B. C22 connectors are now standard on PowerEdge
- C. Allow for higher exhaust temperatures
- D. Enable linking together power supplies

Correct Answer: A

Reference: [https://i.dell.com/sites/csdocuments/Product\\_Docs/en/dell\\_emc\\_poweredge\\_mx7000\\_technical\\_guide.pdf](https://i.dell.com/sites/csdocuments/Product_Docs/en/dell_emc_poweredge_mx7000_technical_guide.pdf)

---

### QUESTION 3

A technician has replaced an MX chassis tub. They complete the tub installation and power on the chassis. They notice that the KVM is no longer functional. What should the technician do after confirming the KVM feature is still enabled in OME-M?

- A. Ensure all cables connecting the tub to the left ear control panel are connected properly
- B. Ensure all power supplies are connected and powered-on
- C. Ensure all cables connecting the tub to the right ear control panel are connected properly
- D. Ensure all installed Management Modules are connected to the network

Correct Answer: A

---

### QUESTION 4



Which feature requires an iDRAC Enterprise license for an MX sled?

- A. iDRAC Service Module
- B. Last Crash Screen
- C. Group Manager
- D. Storage Management

Correct Answer: C

Reference: [https://i.dell.com/sites/csdocuments/Product\\_Docs/en/poweredge-mx740c-technical-guide.pdf?newtab=true](https://i.dell.com/sites/csdocuments/Product_Docs/en/poweredge-mx740c-technical-guide.pdf?newtab=true) (p.9)

---

#### QUESTION 5

An administrator has been tasked with specifying hardware for a deployment having the following requirements:

4 node cluster within a single MX7000 chassis Each node needs a minimum of 6x 2.5" drives 3 TB of memory and 64 physical CPU cores per node

What is the maximum hardware configuration that meets the requirements?

- A. MX740c with no storage sleds
- B. MX740c with MX5016s storage sleds
- C. MX840c with no storage sleds
- D. MX 840c with MX5016s storage sleds

Correct Answer: D

[DES-4421 PDF Dumps](#)

[DES-4421 Study Guide](#)

[DES-4421 Braindumps](#)