

H31-341^{Q&As}

HCIP-Transmission V2.5

Pass Huawei H31-341 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/h31-341.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.pass4itsure.com/h31-341.html

2024 Latest pass4itsure H31-341 PDF and VCE dumps Download

QUESTION 1

Which of the following statements about the electrical-layer overhead processing - source function are correct?

- A. The OPUk performs client signal mapping, frequency adjustment, and rate adaptation in the transmit direction.
- B. The ODUkT calculates the BIP-8 and writes the it into the TCMi.
- C. OTUk calculates BIP-8 and writes it into SM, GCCO, FAS, and MAFS.
- D. The ODUkP calculates overheads such as BIP-8, PM, and GCC1/2.

Correct Answer: C

QUESTION 2

Which of the following ROADM boards have WSS optical modules?

- A. RDU9
- B. WSM9
- C. WSMD9
- D. WSD9

Correct Answer: B

QUESTION 3

Dispersion compensation is not required for 40 Gbit/s and 100 Gbit/s coherent systems because the dispersion tolerance of coherent boards is large. NG WDM products do not support hybrid transmission of non-coherent and coherent networks.

- A. True
- B. False

Correct Answer: B

QUESTION 4

The causes of discrete services are as follows:

- A. The cross-connection configuration on the NE is incorrect.
- B. The logical fiber connection of the NE is inconsistent with the physical fiber connection.
- C. The configuration data on the NE side is not uploaded to the U2000.



https://www.pass4itsure.com/h31-341.html

2024 Latest pass4itsure H31-341 PDF and VCE dumps Download

D. A subnet service whose source or sink port is not in the management scope of the U2000 is available.

Correct Answer: C

QUESTION 5

In a WDM system, after a distance of transmission, the OSNR of the signals at the receive end decreases to a certain extent. Which of the following is the main cause?

- A. Use of EDFA
- B. The fiber attenuation is too large.
- C. New optical fiber is not used.
- D. Use of Demultiplexer Multiplexer

Correct Answer: B

Latest H31-341 Dumps

H31-341 Practice Test

H31-341 Braindumps