300-180^{Q&As}

Troubleshooting Cisco Data Center Infrastructure

Pass Cisco 300-180 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass4itsure.com/300-180.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

While performing an upgrade to Cisco UCS Release 2.2, the traffic in several VLANs is no longer active. What is the cause of this issue?

A. Ethernet and FCoE VLANs cannot be configured on the same Cisco UCS domain.

B. The UCS Manager detected overlapping VLANs during the upgrade, and Ethernet traffic on those VLANs is now dropped.

C. The UCS Manager needs to be rebooted to force the configuration to work properly.

D. Ethernet and FCoE VLANs cannot be configured different Cisco UCS domain.

Correct Answer: B

QUESTION 2

Which option is the cause when a DIMM is marked as bad?

A. More than 16000 errors were witnessed during test execution during BIOS.

B. DIMM Blacklisting is enabled.

C. The DIMM is missing.

D. The bank of DIMMs is composed of different size DIMMs.

Correct Answer: A

QUESTION 3

Refer to the exhibit.


```
N7k-1# show ip ospf neighbor

Neighbor ID Pri State          Dead Time  Address     Interface
10.10.1.2   1   EXCHANGE/   -  00:00:26   10.10.1.2   Ethernet1/1

Nk7-2# show ip ospf neighbor

Neighbor ID Pri State          Dead Time  Address     Interface
10.10.1.1   1   EXSTART/    -  00:00:23   10.10.1.1   Ethernet2/3
```

The two switches are stuck in the EXCHANGE and EXSTART states. Which option is a possible cause of the issue?

A. The subnet mask is mismatched.

B. The interfaces are not connected.

C. The MTU is mismatched.

D. The IP address of the OSPF process is incorrect.

Correct Answer: C

QUESTION 4

A customer is troubleshooting FCoE in its network and sees pause counters increasing when it runs the command show interface eth1/5. What is the cause of this?

A. The CNA connected to the switch is sending Xon or Xoff PFC frames.

B. The HBA connected to the switch is sending Xon or Xoff PFC frames.

C. Pause counters increase regularly; there is nothing to be concerned about.

D. A firmware upgrade on the Fibre Channel adapter that is connected to the switch will fix this issue.

Correct Answer: A

QUESTION 5

Refer to the exhibit. Which statement about how the MAC addresses replicate is true?

A. The MAC addresses replicate from fabric interconnect 1 to fabric interconnect 2. Fabric interconnect 2 installs the MAC addresses if fabric interconnect 1 fails

B. The learned MAC addresses of fabric interconnect 1 must be relearned by fabric interconnect 2 if fabric interconnect 1 fails

C. The MAC addresses replicate from fabric interconnect 1 to fabric interconnect 2. Fabric interconnect 2 installs the

MAC addresses immediately

D. The learned MAC addresses of the active fabric interconnect replicate only if the active fabric interconnect fails

Correct Answer: D

300-180 VCE Dumps   300-180 Study Guide   300-180 Braindumps

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications.
You can view Vendor list of All Certification Exams offered:

https://www.pass4itsure.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: