6103 ^{Q&As}

Avaya ERS 8000 and Avaya VSP 9000 Implementation Exam

Pass Avaya 6103 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass4itsure.com/6103.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

🔘 **Instant Download** After Purchase

🔘 **100% Money Back** Guarantee

🔘 **365 Days** Free Update

🔘 **800,000+** Satisfied Customers

QUESTION 1

Using Enterprise Device Manager, the technician opens the ERS 8000 switch and sees that there are five ports showing with an orange light.

What does the orange light indicate?

A. The Ports have no link.

B. The Ports are in standby mode.

C. The Ports are being tested.

D. The Ports are manually disabled.

Correct Answer: B

QUESTION 2

What is the minimum number of Switch fabric (SF) cards the VSP 9000 R3.1 needs to have installed?

A. 1

B. 2

C. 3

D. 4

Correct Answer: C

QUESTION 3

A customer is expressing concern about reliability for their single uplink connections to the wiring closet. The switches in the wiring closet support Distributed Multi-Link Trunking (DMLT).

What can be done so the Virtual Services Platform (VSP) 9000 can eliminate a single point of failure for the lowest cost?

A. Add a second switch fabric module.

B. Duplicate the trunk elements in software.

C. Duplicate the trunks across separate modules using DMLT.

D. Configure multiple VSP 9000 switches using Split Multi-Link Trunking (SMLT).

Correct Answer: C

QUESTION 4

After a chassis failure, you replace the Avaya Ethernet Routing Switch 8800/8600 with a new chassis that has a new base MAC address. To transfer the existing license to this new chassis you must have the new base MAC address.

Which CLI command will show you the base MAC address of your new chassis?

A. show sys-info

B. show sys base-mac

C. display sys info

D. info sys base-mac

Correct Answer: A

QUESTION 5

Flight Recorder can be used on the Virtual Services Platform (VSP) 9000 to help Identify problems. When can a Flight Recorder snapshot be taken?

A. when the VSP has to be booted into the diagnostic mode

B. only after a warning message is logged

C. anytime

D. every hour

Correct Answer: B

6103 VCE Dumps   6103 Practice Test   6103 Braindumps