E20-616 ^{Q&As}

Symmetrix Installation and Troubleshooting Specialist

Pass EMC E20-616 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass4itsure.com/e20-616.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Which component types are installed in a VMAX 10K Storage Bay?

A. DAE, PDP, PDU, LCC

B. DAE, PDP, PDU, SPS

C. LCC, SPS, PDP, PDU

D. DAE, FAN, PDU, SPS

Correct Answer: A

QUESTION 2

Refer to the Exhibit.

You are Enabling SMC on the Service Processor. Into which Ethernet port do you plug the IP cable?

A. 8

B. 7

C. 6

D. 5

Correct Answer: A

QUESTION 3

While running the Backend Cabling Verification script, the LEDs do not match the SymmWin graphic. It halts with a message that there is a cabling error and advises moving cables. Which service engagement would require PSE intervention prior to moving the cables?

A. Data center move

B. Installation

C. DAE addition

D. Storage bay addition

Correct Answer: A

QUESTION 4

You installed Symmwin on your service laptop. You tried to run the command A7,C to verify the status of

the devices, but the Inlines icon is disabled. What needs to done to successfully complete this activity?

A. Move to the VMAX service processor.

B. Log in with the Engineering account.

C. Use the Tools menu dropdown and choose Inlines.

D. Change the access level to Expert.

Correct Answer: A

QUESTION 5

What is the vault hyper size in GB for configuring a new VMAX 20K?

A. 5

B. 9

C. 4.5

D. 0.5

Correct Answer: A

Latest E20-616 Dumps   E20-616 PDF Dumps   E20-616 Braindumps