VCE & PDF
Pass4itSure.com

https://www.pass-itsure.com/ns0-191.html
2022 Latest pass4itsure NS0-191 PDF and VCE dumps Download

NS0-191^{Q&As}

NetApp Certified Support Engineer

Pass Network Appliance NS0-191 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass4itsure.com/ns0-191.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Network Appliance Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

You are trying to determine why AutoSupport notifications are not being sent. Which two types of output would be used first to solve this problem? (Choose two.)

A. the MGWD.log

B. the notifyd.log

C. output of theautosupport history showcommand

D. output of thenetwork interface showcommand

Correct Answer: BC

QUESTION 2

Click the Exhibit tab.


```
FILER01:
Sat Mar 12 11:28:12 CET [filer01:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv' failed.
Sat Mar 12 11:28:12 CET [filer01:rv.connection.torndown:info]: HA interconnect: cfo_rv1 is torn
down on NIC 1.
Sat Mar 12 11:28:12 CET [filer01:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv1' failed.
Sat Mar 12 11:28:12 CET [filer01:rv.connection.torndown:info]: HA interconnect: cfo_rv2 is torn
down on NIC 1.
Sat Mar 12 11:28:12 CET [filer01:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv2' failed.
Sat Mar 12 11:28:19 CET [filer01:bridge.removed:info]: FC-to-SAS bridge site3_3:13.126L0 [ATTO
FibreBridge6500N 1.61] S/N [FB6500N108245] was removed.
Sat Mar 12 11:28:19 CET [filer01:bridge.removed:info]: FC-to-SAS bridge site3_3:5.126L0 [ATTO
FibreBridge6500N 1.61] S/N [FB6500N111508] was removed.
```

```
FILER02:
Sat Mar 12 11:28:12 CET [filer02:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv' failed.
Sat Mar 12 11:28:14 CET [filer02:rv.connection.torndown:info]: HA interconnect: cfo_rv2 is torn
down on NIC 1.
Sat Mar 12 11:28:14 CET [filer02:rv.connection.torndown:info]: HA interconnect: cfo_rv1 is torn
down on NIC 1.
Sat Mar 12 11:28:14 CET [filer02:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv2' failed.
Sat Mar 12 11:28:14 CET [filer02:cf.rv.notConnected:error]: HA interconnect: Connection for
'cfo_rv1' failed.
Sat Mar 12 11:28:17 CET [filer02:bridge.removed:info]: FC-to-SAS bridge site1_2:13.126L0 [
FibreBridge6500N 1.61] S/N [FB6500N108709] was removed.
Sat Mar 12 11:28:17 CET [filer02:bridge.removed:info]: FC-to-SAS bridge site1_2:5.126L0 [
FibreBridge6500N 1.61] S/N [FB6500N105093] was removed
```

Your customer\'s MetroCluster controllers have generated AutoSupport notifications with a "DISK REDUNDANCY FAILED" message. Referring to the exhibit, which component is causing the problem?

A. the SAN switch site3_3

B. the SAN switch site1_2

C. the ATTO bridges on site3

D. the inter-switch link (ISL) between site1 and site3

Correct Answer: D

QUESTION 3

A customer is using DP SnapMirror replication between two clusters. The source cluster is using Clustered Data ONTAP 8.2.3.

Which two versions are acceptable for the destination cluster to be operating? (Choose two.)

A. 8.1.4

B. 8.0.2

C. 8.3.1

D. 8.2.3

Correct Answer: AD

QUESTION 4

A customer cannot create a new volume from OnCommand System Manager.

Which two clustered Data ONTAP daemons would be at fault in this scenario? (Choose two.)

A. secd

B. bcomd

C. mgwd

D. v1db

Correct Answer: AB

QUESTION 5

Click the Exhibit tab. cluster::> network port show Node Port Ipspace Broadcast Domain Link MTU Admin/Open

node1

e0a Cluster Cluster up 9000 auto/1000

e0b Cluster Cluster up 9000 auto/1000

e0c Default Default up 1500 auto/1000

e0d Default Default up 1500 auto/1000

e0e Default Default up 1500 auto/1000

e0f Default Default up 1500 auto/1000

e0g Default Default up 1500 auto/1000

node2

e0a Cluster Cluster up 9000 auto/1000

e0b Cluster Cluster up 9000 auto/1000

e0c Default Default up 1500 auto/1000

e0d Default Default up 1500 auto/1000

e0e Default Default up 1500 auto/1000

e0f Default Default up 1500 auto/1000

e0g Default Default up 1500 auto/1000

A customer contracts you and asks for assistance in determining which ports can be used for a new broadcast domain on a clustered Data ONTAP 8.3.2 system. The system is serving LUNs using the FC protocol and is in production.

However, for Ethernet traffic, it is not yet in production. The customer provides you the output of the network port show command.

Referring to the exhibit, which ports will be eligible to create a new broadcast domain without impacting production storage virtual machines (SVMs) serving FC LUNs?

A. any port in theClusterbroadcast domain on node1 and node2

B. any port on node1

C. any port in theDefaultbroadcast domain on node1 and node2

D. any port on node2

Correct Answer: C

[NS0-191 PDF Dumps](#)   [NS0-191 Study Guide](#)   [NS0-191 Braindumps](#)

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications.
You can view Vendor list of All Certification Exams offered:

https://www.pass4itsure.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: