100% Money Back Guarantee

Vendor: HP

Exam Code: HP3-042

Exam Name: HP LaserJet 5200 Series Printers Service and Support

Version: Demo

QUESTION NO: 1

How many motors do HP LaserJet 5200 series printers contain?

A. 1
B. 2
C. 3
D. 4

Answer: D

QUESTION NO: 2

What printer drivers are included on the inbox CD for the HP LaserJet 5200 series printer? Select THREE.

A. Linux
B. PCL 5e
C. PostScript 3
D. PCL 6

Answer: B,C,D

QUESTION NO: 3

When removing/replacing the assembly, for which internal assembly must you first remove the cartridge door unit?

A. control panel assembly
B. laser/scanner assembly
C. face down delivery unit
D. cassette-paper pickup unit

Answer: B

QUESTION NO: 4

Which of the following are customer self-repair parts? Select THREE.

A. tray 1 pickup roller

B. formatter

C. memory DIMMs

D. main fan duct

Answer: A,B,C

QUESTION NO: 5

The HP LaserJet 5200L comes with which two of the following? Select TWO.

A. 500-sheet input tray

B. one open DIMM slot

C. duplex unit

D. hi-speed USB 2.0 port

Answer: B

QUESTION NO: 6

What type of page would you print for information about jams, loading trays, or supported media types and sizes?

A. Show Me How

B. Configuration

C. Device Information

D. Self-help

Answer: A

QUESTION NO: 7

Which unit, or units, must be removed when removing the high-voltage power supply?

A. cartridge door unit

B. registration unit

C. both the cartridge door unit and the registration unit

D. neither the cartridge door unit nor the registration unit

QUESTION NO: 8

What is the heaviest paper supported in trays 2 and 3 on the HP LaserJet 5200 series printer?

A. 75 g/m2 (20 lb)
B. 90 g/m2 (24 lb)
C. 120 g/m2 (32 lb)
D. 199 g/m2 (53 lb)

Answer: C

QUESTION NO: 9

What happens if the formatter and DC controller are replaced at the same time?

A. The NVRAM remains blank and the printing device needs to be reset.
B. The 'Save and Restore' feature does not properly store new memory on the NVRAM.
C. The printing device perceives the DC controller as being reused, and rejects the new controller.
D. The printing device does not recognize the newly applied serial number, and does not come to a 'Ready' state during power-up.

Answer: D

QUESTION NO: 10

After a formatter is replaced, how much time is needed after the device comes to 'Ready' for the NVRAM settings to be rewritten?

A. 1 minute
B. 3 minutes
C. 5 minutes
D. 7 minutes

Answer: C

To Read the **Whole Q&As**, please purchase the **Complete Version** from **Our website**.

Trying our product !

★ **100%** Guaranteed Success

★ **100%** Money Back Guarantee

★ **365 Days** Free Update

★ **Instant Download** After Purchase

★ **24x7** Customer Support

★ Average **99.9%** Success Rate

★ More than **69,000** Satisfied Customers Worldwide

★ Multi-Platform capabilities - **Windows, Mac, Android, iPhone, iPod, iPad, Kindle**

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket:

Guarantee & Policy | Privacy & Policy | Terms & Conditions