

642-980^{Q&As}

Troubleshooting Cisco Data Center Unified Fabric

Pass Cisco 642-980 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/642-980.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.pass4itsure.com/642-980.html

2022 Latest pass4itsure 642-980 PDF and VCE dumps Download

QUESTION 1

On the Cisco Nexus 7000 Series Switch, what could be the reason why the (config- vlan)#private-vlan primary command fails?

- A. There are not enough resources in the VDC.
- B. You are using a reserved VLAN ID.
- C. The VLAN is a secondary VLAN.
- D. The interface is in the wrong VRF.
- E. The PVLAN feature is not enabled.
- F. The VLAN does not exist.

Correct Answer: E

QUESTION 2

There is an ARP storm in VDC 1. Some users on VDC 2 notice that ARP is not resolving for their gateway on the Cisco Nexus core. What is the cause?

- A. The ARP CoPP class committed information rate is exceeded, resulting in ARP loss in all VDCs.
- B. The administrator has not correctly configured the ARP CoPP class in VDC 2.
- C. The ARP traffic in VDC 1 is copied to the host ports in VDC 2, causing overutilization and output discards.
- D. Because the ARP process in the default VDC (VDC 1) is responsible for processing ARP traffic for all VDCs, VDC 2 will be affected.

Correct Answer: A

QUESTION 3

In a Cisco Data center network, what troubleshooting step would you do first when having a npv issue?

- A. Check to see if npv is enabled
- B. Check name server database to see if it recognizes device
- C. Check detail config of FCNS database
- D. Check the show-tech-support detail

Correct Answer: A

https://www.pass4itsure.com/642-980.html

2022 Latest pass4itsure 642-980 PDF and VCE dumps Download

QUESTION 4

A customer reports that a 10-Gb interface between a Cisco Nexus 7009 Switch and a Cisco Nexus 5548UP Switch is not passing traffic. The Nexus 7009 interface indicates up/up. The Nexus 5548UP interface indicates up/down. Which feature should you enable to help isolate the root cause?

- A. CDP
- B. GOLD
- C. UDLD
- D. DAI
- E. LACP

Correct Answer: C

QUESTION 5

Referto the exhibit. An administrator sees this message in the log while merging switch fabrics. What is theissue?

%ZONE-2-ZS_MERGE_FAILED: %\$VSAN 1%\$ Zone merge failure, isolating interface fc2/1 error: Received rjt from adjacent switch:[reason:0]

%ZONE-2-ZS_MERGE_FAILED: %\$VSAN 1%\$ Zone merge failure, isola# **
interface fc1/2 error: Member mismatch

- A. Two switches have different zone names with the same members.
- B. Two switches have different zone set names with the same members.
- C. Two switches have the same zone set and zone name, but with different members.
- D. Two switches have the same zone set and zone name with the same members.

Correct Answer: C

642-980 PDF Dumps

642-980 Practice Test

642-980 Braindumps



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.pass4itsure.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4itsure, All Rights Reserved.