



CQE^{Q&As}

Quality Engineer Exam

Pass ASQ CQE Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/cqe.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by ASQ Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



**QUESTION 1**

Which of the following distributions have the set of all real numbers as their domain?

- A. Lognormal
- B. Exponential
- C. Weibull
- D. None of the above.

Correct Answer: D

QUESTION 2

A process is turning out end items that have defects of type A or type B or both. If the probability of type A defect is 0.1 and of a type B is 0.2, the probability that an end item will have no defect is

- A. 0.7
- B. 0.30
- C. 0.72
- D. 0.68

Correct Answer: C

QUESTION 3

An operation requires shipments from your vendor of small lots of fixed size. The attribute sampling plan used for receiving inspection should have its OC curve developed using

- A. The binomial distribution.
- B. The Gaussian (normal) distribution.
- C. The Poisson distribution.
- D. The hypergeometric distribution.

Correct Answer: D

QUESTION 4

The MOST essential value of a surface plate in precision measurement application is which of the following?

- A. It provides a flat working surface.



- B. It provides a surface free of minor vibration.
- C. It provides an accurate reference surface.
- D. It provides a chemically resistant work surface.

Correct Answer: C

QUESTION 5

The distribution of a characteristic is negatively skewed. The sampling distribution of the mean for large samples is:

- A. Negatively skewed.
- B. Approximately normal.
- C. Positively skewed.
- D. Lognormal.

Correct Answer: B

[Latest CQE Dumps](#)

[CQE VCE Dumps](#)

[CQE Practice Test](#)