



# H13-341<sup>Q&As</sup>

Huawei Certified internetwork Expert - Transmission

## Pass Huawei H13-341 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/h13-341.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



**QUESTION 1**

Which of the following statements about replacing the SCC board is incorrect?

- A. In the case of the 1+1 hot backup of the SCC board, replacing the control board does not affect services when the active/standby switchover is performed.
- B. After the SCC board is removed, the BD\_STATUS and COMMUN\_FAIL alarms are reported. After the new board goes online, these alarms need to be manually cleared.
- C. If the software version of the new SCC board is later than equipment version, clear the database of the SCC board, and then downgrade the software on the SCC board to the same version as the equipment.
- D. If the software version of the new SCC board is earlier than the equipment version, upgrade the software on the SCC board to the same version as the equipment.

Correct Answer: C

---

**QUESTION 2**

MPLS tunnel APS protection supports multiple types of command switching and has different priorities. Which of the following commands switching types has the highest priority?

- A. Locked Switching
- B. Practice Switching
- C. Force Switching
- D. Manual Switching

Correct Answer: C

---

**QUESTION 3**

Which of the following monitoring boards do not support 1588v2 signal processing and transparent transmission?

- A. AST2
- B. SC2
- C. ST2
- D. SC1

Correct Answer: A

---

**QUESTION 4**



Which of the following is not a precaution after board replacement?

- A. Record the settings of jumpers and DIP switches on the board.
- B. For functional units that have backups, check whether the switchover is normal.
- C. Check the indicator blinking status of the board and ensure that the board works properly.
- D. Ensure that no abnormal alarm.

Correct Answer: B

---

#### QUESTION 5

Which of the following statements about MPLS is wrong?

- A. MPLS has two planes: control plane and forwarding plane. The control plane is connection-oriented, the forwarding plane is connectionless.
- B. MPLS is not a service or application. It is a standard routing and switching platform that supports various upper-layer protocols and services.
- C. In the packet transport field, the MPLS technology is mainly used to construct tunnels to carry various types of services (for example, TDM, ATM, and Ethernet) transmitted by PWE3 to implement end-to-end transmission of services on packet networks.
- D. MPLS packet forwarding is based on labels.

Correct Answer: A

[Latest H13-341 Dumps](#)

[H13-341 PDF Dumps](#)

[H13-341 Practice Test](#)