



HP0-S35^{Q&As}

Implementing HP BladeSystem Solutions

Pass HP HP0-S35 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/HP0-S35.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- ⚙ **Instant Download** After Purchase
- ⚙ **100% Money Back** Guarantee
- ⚙ **365 Days** Free Update
- ⚙ **800,000+** Satisfied Customers



**QUESTION 1**

Which action must be performed when adding a processor to an HP ProLiant BL460c server?

- A. Upgrade the firmware on the Smart Array Controller
- B. Add additional memory to Processor one.
- C. Confirm voltage rating on the memory DIMMs
- D. Verify and update system ROM if needed

Correct Answer: D

<http://bizsupport2.austin.hp.com/bc/docs/support/SupportManual/c03231397/c03231397.pdf>

Processor



WARNING: To reduce the risk of personal injury from hot surfaces, allow the drives and the internal system components to cool before touching them.



CAUTION: To prevent possible server malfunction, do not mix processors of different speeds or cache sizes. Refer to the label on the processor heatsink for a description of the processor.



CAUTION: To prevent possible server blade overheating, always populate each processor socket with a processor socket cover and a heatsink blank or a processor and a heatsink.



IMPORTANT: Processor socket 1 must always be populated. If processor socket 1 is empty, the server blade does not power up.

To remove the component:

1. Update the system ROM.

Locate and download the latest ROM version from the HP website (<http://www.hp.com/support>). Follow the instructions on the website to update the system ROM.

2. Power down the server blade (on page 21).
3. Remove the server blade (on page 22).
4. Remove the access panel ("Access panel" on page 23).
5. Remove the heatsink ("Heatsink" on page 46).

**QUESTION 2**

What memory protection is available to a BL460c Gen 8? (Select 4)

- A. Lockstep
- B. Non-Lockstep
- C. Advanced ECC (multi-bit error protection)



D. Memory Mirroring Mode

E. Memory Online Spare Mode

Correct Answer: ACDE

http://h18004.www1.hp.com/products/quickspecs/13706_div/13706_div.PDF

Memory Protection Advanced ECC (multi-bit error protection) Memory Mirroring Mode Memory Lock-Step Mode
Memory Online Spare Mode supported on Intel Xeon 5600 Series processors

QUESTION 3

Which services does HP offer to help you review current firmware levels and develop an appropriate management strategy? (Select two)

A. HP BladeSystem Firmware and Driver Update Process Review

B. HP Startup BladeSystem c-Class Enhanced Networks Service

C. HP Startup BladeSystem c-Class Infrastructure Service

D. HP BladeSystem Release Set

E. HP BladeSystem Firmware and Driver Gap Analysis

Correct Answer: AE

<http://h20000.www2.hp.com/bc/docs/support/SupportManual/c02225412/c02225412.pdf> - Page HP Firmware Management Services overview HP firmware management tools and the HP CloudSystem Matrix Compatibility enable you to apply updates with minimal research or interaction.

However, in many environments it is prudent to have an update strategy that considers the significance of the systems and applications, the company's preference for stability versus innovation, and the sensitivity to downtime. HP offers the following fee-based services to help you review the current firmware, software, and driver levels and develop an appropriate management strategy:

HP BladeSystem Firmware and Driver Gap Analysis HP BladeSystem Firmware and Driver Update Process Review

QUESTION 4

In an HP ProLiant Gen8 server, which additional information does Agentless Management Service Provide to the iLO Management Engine?

A. Memory

B. CPU

C. Temperature

D. Power Supply

Correct Answer: C



QUESTION 5

An engineer installs four HP Virtual Connect Flex-10 10 Gb Ethernet modules into a c7000 enclosure. What is required to enable all Ethernet NICs on all servers to have access to any Virtual Connect Ethernet module uplink port?

- A. External stacking links between the interconnects
- B. Virtual Connect Enterprise Manager license
- C. HP Insight Control central management server (CMS)
- D. Internal stacking link enablement for all modules in the Onboard Administrator interface

Correct Answer: A

Reference:

<http://bizsupport2.austin.hp.com/bc/docs/support/SupportManual/c03478426/c03478426.pdf> Single enclosure stacking diagram

[HP0-S35 PDF Dumps](#)

[HP0-S35 Practice Test](#)

[HP0-S35 Exam Questions](#)



To Read the [Whole Q&As](#), please purchase the [Complete Version](#) from [Our website](#).

Try our product !

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - [Windows](#), [Mac](#), [Android](#), [iPhone](#), [iPod](#), [iPad](#), [Kindle](#)

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

<https://www.pass4itsure.com/allproducts>

Need Help

Please provide as much detail as possible so we can best assist you.

To update a previously submitted ticket:



| | | |
|---|---|--|
|  One Year Free Update Free update is available within One Year after your purchase. After One Year, you will get 50% discounts for updating. And we are proud to boast a 24/7 efficient Customer Support system via Email. |  Money Back Guarantee To ensure that you are spending on quality products, we provide 100% money back guarantee for 30 days from the date of purchase. |  Security & Privacy We respect customer privacy. We use McAfee's security service to provide you with utmost security for your personal information & peace of mind. |
|---|---|--|

Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4itsure, All Rights Reserved.