

HP0-S35^{Q&As}

Implementing HP BladeSystem Solutions

Pass HP HP0-S35 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/HP0-S35.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.pass4itsure.com/HP0-S35.html

2022 Latest pass4itsure HP0-S35 PDF and VCE dumps Download

QUESTION 1

Two Virtual Connect FlexFabric modules are installed in a new HP BladeSystem c7000 solution. Virtual Connect Manager reports the domain as degraded and the stacking links failed. What should be done to correct the problem?

- A. Install Virtual Connect Enterprise Manager
- B. Manually create the stacking links using Virtual Connect Manager
- C. Use the Onboard Administrator to pair the Virtual Connect Modules with each other
- D. Remove the SFPs from x7 and x8 each Virtual Connect Modules

Correct Answer: D


http://h20000.www2.hp.com/bc/docs/support/SupportManual/c02616817/c02616817.pdf - Page

Virtual connect Flex-10 Uplink Port Mappings

It is important to note how the external uplink ports on the Flex-10 module are configured. The graphic below outlines the type and speed each port can be configured as.

- Ports X1 X8; Can be configured as 1Gb or 10Gb Ethernet
- Ports X7 X8; Are also shared as internal cross connect and should not be used for external
 connections, at the very least one horizontal stacking link is required, if modules are in
 adjacent bays.
- Uplink Ports X1-X8 support 0.5–7m length DAC as stacking or uplink
- The CX-4 connection is shared with port X1, only one of these connections, either the CX-4 or SFP+ X1, can be used at a time.

Figure 1 - Flex-10 Module port configuration, speeds and types





https://www.pass4itsure.com/HP0-S35.html

2022 Latest pass4itsure HP0-S35 PDF and VCE dumps Download

QUESTION 2

Which items can be configured using the HP BladeSystem Insight Display? (Select two)

- A. reset iLO password
- B. EBIPA
- C. enclosure name
- D. Sea of Sensors
- E. Insight Display Lockout PIN

Correct Answer: CE

QUESTION 3

When connecting an HP BladeSystem to a HP P4000 Storage System, which iSCSI initiator is required?

- A. Initiator provided by ProLiant Support Pack (PSP)
- B. MPIO iSCSI initiator pack included in the iSCSI connectivity kit CD
- C. Native iSCSI initiator provided by the OS vendor
- D. MPX200 iSCSI initiator target driver kit
- E. iSCSI initiator from the HP P4000 Solution Pack CD

Correct Answer: C

QUESTION 4

What is used to increase the logical drive size in an HP Smart Array controller installed in an HP ProLiant server?

- A. DISKPART
- B. EXPAND
- C. ACU CLI
- D. ORCA

Correct Answer: C

http://www.tricksguide.com/how-to-expand-array-extend-logical-drive-raid-hp-acu.html

QUESTION 5

What should be used to improve iSCSI performance especially for large block application?



https://www.pass4itsure.com/HP0-S35.html

2022 Latest pass4itsure HP0-S35 PDF and VCE dumps Download

- A. jumbo frame and switches with large buffers
- B. Ethernet switches with minimal buffers store and forward enabled
- C. Ethernet switches with minimal buffers and 1500 MTU
- D. a VLAN for every iSCSI path, separating devices and LUNs

Correct Answer: A

Latest HP0-S35 Dumps

HP0-S35 Study Guide HP0-S35 Exam Questions



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.pass4itsure.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © pass4itsure, All Rights Reserved.