

## **HPE0-S37**<sup>Q&As</sup>

**Building HPE Server Solutions** 

### Pass HP HPE0-S37 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/hpe0-s37.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



# VCE & PDF Pass4itSure.com

#### https://www.pass4itsure.com/hpe0-s37.html

2024 Latest pass4itsure HPE0-S37 PDF and VCE dumps Download

#### **QUESTION 1**

A customer selects the HPE c7000 with redundant FlexFabric-20/40 F8 Virtual connect modules for a private project. For the server platform, the customer plans to use the ProLiant BL460 Gen9 with the FlexFabric adapters installed.

How many FlexNICs will be	available per 20Gb port for t	he customer\\'s cloud services?
---------------------------	-------------------------------	---------------------------------

A. 1

B. 2

C. 4

D. 8

Correct Answer: B

#### **QUESTION 2**

Which server components are monitored tor redundancy status by means of HPE Agentless Management? (Select two )

A. FlexibteLOM

B. power supply

C. Smart Array controller

D. fans

E. CPU

Correct Answer: BC

#### **QUESTION 3**

Which functionality is enabled by UEFI Boot Mode?

A. secure boot

B. HPE iLO Federation

C. HPE Intelligent Provisioning

D. pre-boot configuration

Correct Answer: B

## QUESTION 4



#### https://www.pass4itsure.com/hpe0-s37.html

2024 Latest pass4itsure HPE0-S37 PDF and VCE dumps Download

A customer needs to modify the configuration of Virtual Connect modules in a c7000 enclosure but when the administrator attempts to access Virtual Connect Manager the administrator is redirected to a different URL.

What is a likely reason for this issue?

- A. The enclosure is managed by HPE OneView.
- B. The stacking link of the HPE Onboard Administrator is disconnected.
- C. The Virtual Connect Manager and HPE Onboard Administrator firmware versions are incompatible.
- D. The Virtual Connect Manager license is not enabled.

Correct Answer: C

#### **QUESTION 5**

A customer needs to eliminate thermal imbalance in its new data center. Which solution should the architect recommended to the customer?

- A. any HPE iPDU
- B. HPE Intelligent Network racks
- C. HPE Rack Air Duck Kit
- D. any Intelligent Series rack

Correct Answer: D

HPE0-S37 PDF Dumps

HPE0-S37 Exam Questions

**HPE0-S37 Braindumps**