



H35-211^{Q&As}

HCIP-Access V2.5

Pass Huawei H35-211 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/h35-211.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

When configuring IPTV services on the U2000, what templates are included in the IGMP templates?

- A. Permission templates
- B. Multicast user templates
- C. Program templates
- D. Preview the parameter template

Correct Answer: ACD

QUESTION 2

(Multi-select) Query PPPOE simulation results on the MDU side as follows From the query results, it can be judged ()

- A. The service configuration of ppPoE users is normal
- B. PPPoE user account and authentication method are correct
- C. The link between MDU tone setting and BRAS is ok
- D. The MDU management IP is configured correctly

Correct Answer: ABC

QUESTION 3

(single) In the FTTx service networking and data planning, user security should be considered. Which of the following measures can prevent user attacks?

- A. Use anti-mac to solve
- B. Defense IP spoofing
- C. User Layer 2 isolation and controlled mutual visits
- D. Identify the user with port physical information

Correct Answer: C

QUESTION 4

(multiple) Which of the following are the methods and ideas for XDSL dialup abnormal fault location?

- A. MODEM ATM package format



- B. Confirm that the MODEM configuration is correct
- C. Query the traffic of the xDSL port to determine whether there is normal traffic between the terminal and the terminal.
- D. Confirm whether the gateway can be pinged from the client.

Correct Answer: ABCD

QUESTION 5

(single) When locating ADSL/ADSL2+ failure, which of the following reasons may cause the user to make a call but not to access the Internet?

- A. Line configuration template interleaving depth configuration is unreasonable
- B. ADSL Modem failure
- C. User external line interruption
- D. None of the above

Correct Answer: B

QUESTION 6

(single) Which process message does the Radius protocol packet of Code=3 belong to?

- A. Requesting the certification process
- B. Requesting the billing process
- C. Certification rejection process
- D. Billing response process

Correct Answer: C

QUESTION 7

(single) Is the following description correct?

The minimum activation rate (Minimum transmission rate) in the ADSL/ADSL2+ parameter indicates the minimum activation rate that must be reached in this direction after the line is activated. If the setting is too large, the modem may not be activated normally.

- A. True
- B. False

Correct Answer: A

**QUESTION 8**

(single) The MA5680T needs to classify traffic flows before performing traffic scheduling. Which of the following options is not available as a means of classifying the MA5680T?

- A. 802.1P cos field
- B. Tos field of IP account message
- C. DSCP field of IP packet
- D. EXP field of MPLS packets

Correct Answer: D

QUESTION 9

(single) Regarding the MA5680T DHCP emulation test function, which of the following statements is incorrect?

- A. The system can only support one-way simulation at the same time.
- B. Execute in TSET mode
- C. Only supports Layer 2 DHCP mode emulation, does not support Layer 3 RELAY emulation
- D. The VLAN of the service flow cannot be QinQ, Stacking, subvlan.

Correct Answer: B

QUESTION 10

(single) The UA5000 supports the SIP protocol. When the SIP AG accesses the IMS network, which device is connected to the IMS?

- A. AGCF
- B. S-CSCF
- C. I-CSCF
- D. P-CSCF

Correct Answer: D

QUESTION 11

In the multiple) GPON network, which of the following reasons may cause the ONT to not be automatically discovered?

- A. The optical power received by the ONT is greater than the overload optical power.



- B. The optical power received by the ONT is less than the sensitivity value.
- C. The ONT auto-discovery function of the GPON port is not enabled.
- D. OLT uplink port down

Correct Answer: ABC

QUESTION 12

(Radio) The following is not the QOS service model, is

- A. Diffserv
- B. Intserv
- C. FIFO service
- D. Best Effort

Correct Answer: A

QUESTION 13

(single) The ADSL user under the UA5000 originally used the activation template as 2M, and then changed the activation template to 4M. The speed throw was maintained at the original level, and there was no obvious improvement. What are the reasons for this problem?

- A. There is congestion in the uplink port
- B. ADSL port has poor external line quality
- C. The depth of the interleaving depth of the active template is too deep
- D. The above are possible

Correct Answer: D

QUESTION 14

(single) Is the following description correct?

The MSAN is connected to the lanswitch GE or the FE. The working mode of the two ports can be either auto-negotiation mode or mandatory mode.

- A. True
- B. False

Correct Answer: B



QUESTION 15

(single) Is the following description correct?

Under IGMP snooping, two users on the OLT broadcast the same program, and the OLT sends two join messages to the multicast router.

A. True

B. False

Correct Answer: A

[H35-211 PDF Dumps](#)

[H35-211 Practice Test](#)

[H35-211 Exam Questions](#)