

# 200-401<sup>Q&As</sup>

Managing Industrial Networks with Cisco Networking Technologies (IMINS)

## Pass Cisco 200-401 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.pass4itsure.com/200-401.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



### https://www.pass4itsure.com/200-401.html

2024 Latest pass4itsure 200-401 PDF and VCE dumps Download

#### **QUESTION 1**

With what are APC connectors used?

- A. Category 6a cables that need tight radius bends
- B. copper network cables in corrosive environments
- C. single-mode fiber-optic cables to reduce return loss
- D. high-density copper patch panels

Correct Answer: C

#### **QUESTION 2**

What are two recommended tools or commands that allow you to troubleshoot connectivity between two devices in different IP networks? (Choose two.)

- A. show interface status
- B. show spanning-tree
- C. ping
- D. show interfaces gigabitEthernet x/y switchport
- E. traceroute
- F. show interface

Correct Answer: CE

#### **QUESTION 3**

According to the Purdue Reference Model, at which layer would you perform manufacturing operations and control?

- A. Level 0
- B. Level 1
- C. Level 2
- D. Level 3
- E. Level 4

Correct Answer: D

### https://www.pass4itsure.com/200-401.html

2024 Latest pass4itsure 200-401 PDF and VCE dumps Download

#### **QUESTION 4**


You are a called upon to troubleshoot connectivity problems to a network device on a production floor. You have used ping and traceroute to verify that you cannot connect to the device from the management network. The network is 209.165.202.128/27 and the device has been given the IP address 209.165.202.158 and mask 255.255.255.224. You have verified that you can reach the device with your computer connected to the same switch as the device. What could be the cause of this problem?

- A. The device is set to the wrong subnet mask.
- B. The device is set to the wrong IP address.
- C. The device has no IP default gateway.
- D. The device is connected to a switchport in the wrong VLAN.

Correct Answer: C

#### **QUESTION 5**

Exhibit: Refer to the exhibit. CCNA.com has the industrial network shown in the exhibit. All switches are configured as layer 2 switches and are using VLAN 1 as their management VLAN. Each VLAN 1 interface has been assigned the correct IP address. What is the purpose of assigning a default gateway to SW-C switch?



A. allows connectivity between the VLAN 1 interface on SW-C and other devices in the network.

- B. allows connectivity between Host A and other devices in the network.
- C. allows connectivity between Host B and other devices in the network.
- D. allows the switch to pass traffic between Host A and Host B

Correct Answer: A



# https://www.pass4itsure.com/200-401.html 2024 Latest pass4itsure 200-401 PDF and VCE dumps Download

200-401 VCE Dumps

200-401 Exam Questions

200-401 Braindumps