



# ISS-003<sup>Q&As</sup>

Intel Server Specialist Certification Exam

## Pass CompTIA ISS-003 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.pass4itsure.com/iss-003.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA  
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



**QUESTION 1**

A customer has a server based on the Intel Server System R2312WTTYS with the RAID C600 Upgrade Key RKSATA4R5, running Microsoft Windows 2012 R2. The customer has been using it for more than six months as the company's primary domain controller, and recently it has started randomly rebooting. Which of the following are relevant tools to use to find the cause of the issues? (Select ALL that apply).

- A. Windows Sysinfo utility
- B. Intel low level debug utility
- C. BIOS debug using IPT
- D. Windows event log
- E. EFI SELView utility
- F. EFI Syscfg utility
- G. Intel Raid Web Console debug toolkit

Correct Answer: ADE

---

**QUESTION 2**

Your customer has asked you the Intel Server Specialist for confirmation on the process following changes to their server (additional memory, a different raid card and a 40Gb Ethernet card)? What must they do to ensure accurate monitoring of all the sensors in their S2600WT based server?

- A. The FRU/SDR must be updated with the latest master.cfg to enable the new hardware to be detected.
- B. They don't need to do anything - the current firmware will auto-configure.
- C. The ME must be updated prior to use of the master.cfg and then the FRUSDR update may be carried out.
- D. Only the FRU needs to be updated as the SDR now auto-configures
- E. Only the SDR needs to be updated as the FRU auto-configures.

Correct Answer: B

---

**QUESTION 3**

Your customer is asking you as an Intel Server Specialist for some clarification on RAID arrays on the Grantley generation of server products. In particular they need to know which RAID levels can be achieved on S2600CW2S. How would you advise your customer from the list below?

- A. 0, 1, 1E
- B. 0, 1, 1E, 10, 5 through the upgrade key AXXRPFKHY5



C. C.0, 1, 10, 5, 6

D. 0, 1, 1E, 10, 5, 50 through the upgrade key AXXRPFKHY5 E. 0, 1, 10,

Correct Answer: D

---

#### QUESTION 4

An Intel® Server Specialist is helping a customer configure their RAID using the Intel® RAID Web Console. The Specialist advises the customer to use Auto-Configuration Mode as it automatically creates the best possible RAID-configuration for the available hardware. Which of the following configurations are NOT supported using this mode? (Select ALL that apply).

- A. Auto Configuration cannot be used when using more than one backplane.
- B. Auto Configuration cannot be used with SSD drives.
- C. Auto Configuration cannot be used for RAID 10, 50, or 60.
- D. Auto Configuration cannot be used for creating RAID on 2 HDDs.
- E. Auto Configuration cannot be used with mixed SATA and SAS drives.

Correct Answer: CE

---

#### QUESTION 5

A reseller would like to confirm that the chassis fans for an Intel Server Chassis are connected to the correct headers on the installed Intel Server Board. Which of the following documentation could be used to obtain this information?

- A. The Quick Start Guide for the Intel Server Board shows the required connections.
- B. The TPS for the Intel Server Chassis will contain details for the fans included in the specific chassis.
- C. The technical specifications of the Intel Server Board will show the proper connections.
- D. The TPS for the Intel Server Board will contain details for the fan headers for the specific server board.

Correct Answer: A

[Latest ISS-003 Dumps](#)

[ISS-003 VCE Dumps](#)

[ISS-003 Brindumps](#)