# RCDD<sup>Q&As</sup>

BICSI Registered Communications Distribution Designer - RCDDv14

## Pass BICSI RCDD Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.pass4itsure.com/rcdd.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by BICSI Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



### https://www.pass4itsure.com/rcdd.html

2024 Latest pass4itsure RCDD PDF and VCE dumps Download

#### **QUESTION 1**

What\\'s the RECOMMENDED twisted pair cable slack length to be left at the work area outlet location to enable the possibility of future changes in the Horizontal Cabling System?

A. =0.152 m (0.5 ft)

B. =0.3 m (1 ft)

C. = 1 m (3 ft)

D. = 5m (16 40 ft)

Correct Answer: B

#### **QUESTION 2**

A sponsor decides that the business environment is unfavorable for continuation of a program.

The sponsor asks that the program be closed.

What items should be completed as part of the program\\'s final report?

A. Lessons learned, successes and failures, and financial and performance assessments

B. Final updates to the benefits register, successes and failures, and resource disposition

C. Financial and performance assessments, successes and failures, and reason(s) for program closure

D. Knowledge transition, successes and failures, and reason(s) for program closure

Correct Answer: A

#### **QUESTION 3**

For design purposes, which of the following would be the typical size range of a 4-pair 100 ohm UTP or ScTP (FTP) cable?

A. .50 in to .75 in

B. .14 in to .25 in

C. .31 in to .43 in

D. .11 in to .18 in

Correct Answer: B

## QUESTION 4



#### https://www.pass4itsure.com/rcdd.html 2024 Latest pass4itsure RCDD PDF and VCE dumps Download

Based on the estimated work area size, what is the MAXIMUM number of work areas that a telecommunications enclosure shall serve?

A. 20

B. 26

C. 32

D. 36

E. 40

Correct Answer: D

#### **QUESTION 5**

A program manager is concerned that a program will be unable to achieve its intended benefits. How should the program manager handle this concern?

- A. Meet with the program management office (PMO) lo review critical program success factors.
- B. Meet with the component project managers to reallocate resources within the program
- C. Meet with the program stakeholders to determine if a reduction in program scope is acceptable
- D. Meet with the component project managers to perform risk analysis

Correct Answer: A

Latest RCDD Dumps

RCDD VCE Dumps

RCDD Braindumps