
Exam : HP3-025

Title : HP Laserjet 9000 Series

Version: DEMO

4.If the Jetdirect functionality fails for the HP LaserJet 9050dn, you must ____

B.cycle power to reset the device

C.replace the formatter

D.download new firmware

Answer: B

5. What is the maximum stack height in the accumulator of the 3000-sheet stapler/stacker?

A.2.5 mm

B.no limit

C.5.5 mm

D.5.5 cm

Answer: C

Trying our product!

- ★ 100% Guaranteed Success
- ★ 100% Money Back Guarantee
- ★ 365 Days Free Update
- ★ Instant Download After Purchase
- ★ 24x7 Customer Support
- ★ Average 99.9% Success Rate
- ★ More than 69,000 Satisfied Customers Worldwide
- ★ Multi-Platform capabilities Windows, Mac, Android, iPhone, iPod, iPad, Kindle

Need Help

Please provide as much detail as possible so we can best assist you.

To update a previously submitted ticket:





Guarantee & Policy | Privacy & Policy | Terms & Conditions

Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © 2004-2014, All Rights Reserved.